Notice



Category:	COLOR TELEVISION	Date:	AUGUST / 08 / 2011					
Please add this notice to the Service Manual listed below. REVISION 0								
SERVICE F			FILE NO.					
CORRECTI	ION PRODUCTION CHANGE							

Model: **DP26640M** Effective from : Chassis No. **P26640M-07**

Destination: U.S.A. / CANADA REF : No. SM780181-06

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P26640-06. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P26640-06 used in Model DP26640 (SM780181).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be 02h in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

	Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
anyo Manufacturing Corporation 2011	Page 16, Chassis Electrical Parts List	EL901	Old	1AV4T40C17000	LCD(M260TWR1 R1)	1	NO	D
			New	1AV4T40C05300	LCD(LC260WXN-SBA1)	1	NO	
		EL902	Old	1AV4U20C46200	UNIT, INVERTER	1	NO	D
			New	86632L-0550A-	UNIT, INVERTER	1	NO	
		WK5LV- PN	Old	1AA4W30B66500	LVDS CABLE, 40P-31P	1	NO	D
			New	1LB4W30B25200	LVDS CABLE, 40P-31P	1	NO	
		N/A	Old	N8MK T-CON	N8MK T-CON	1	NO	D
			New	86871L-1603A-	Timing Control Board	1	NO	

© Sanyo Manufacturing Corporation 2011

© Sanyo Manufacturing Corporation 2011

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

August 2011 SMC

Published in Mexico